



# Lead Abatement Info Session

**When:** April 15, 2026

**What Time:** 1 p.m.

**Where:**

Pontiac Michigan Works

1850 N. Perry

Pontiac, MI 48340



## Lead Worker Certification:

No experience required.  
6 months construction-  
related experience  
recommended.



## Lead Supervisor Certification:

2 years construction-  
related experience  
required.



Scan the QR  
code to sign  
up or call  
517-275-2994

Join us to find out how you can become a certified lead professional qualified to work on lead abatement projects. Scan the QR code, call 517-275-2994 or visit us on the web at <https://www.michigan.gov/mileadsafe/events>

A lead abatement project involves removing lead-based paint hazards in homes, buildings and other construction sites, according to the site's "scope of work." Work can involve:

- Changing windows
- Painting
- Wet mopping
- HEPA vacuuming
- Wet scraping
- Removing and replacing lead-contaminated soil